



service bulletin

No. 98-15

Additional Warning Signal - Sport Jet 175XR²

Models Affected

All SPORT JET 175XR² models - 1997 and newer

Serial numbers : 0E203000 & above

There is an additional warning signal for the Sport Jet 175XR² which is not described in the operator's manual. This warning will be added at the next printing.

The warning system for the Sport Jet 175XR² presently has three indicators described in the Operator's manual:

1. One short beep sounds when the ignition key is turned on. This is a system check.
2. A continuous sound indicates an overheat condition.
3. Repeat cycles of four short beeps with a two minute pause and then four short beeps indicate either a low oil level or an oil pump malfunction.

The additional warning is a continuous intermittent beeping sound which varies with engine rpm. This is an **indication of an oil gear related problem**. Refer to Service Bulletin (97-18 Mercury/Mariner, 97-5 Sport Jet, & 97-14 Force) for proper repair procedures.

NOTE: *This bulletin is informational only and is not intended as a service authorization or fix program.*