

## Service Bulletin

## Bulletin No. 2004-61

Circulate to:

Sales Manager

```
Accounting
```

Service Manager

Technician

Parts Manager

## CMD Service Bulletin 2004-01 - 1.7L Injection Pump Timing Adjustment

**Models Affected** 

Application	Model	Serial No.
МСМ	D1.7L DTI	All
CMD	1.7 MS 120 All	
CMD	1.7 MI 120	All

## Situation

For the affected models, the specifications for the injection pump timing adjustments have changed to the values shown in the following table:

Description		Specifications	
Timing Setting	Standard	1.55 mm (0.0610 in.)	
	Limit (Test Value)	1.50-1.60 mm (0.0590-0.0629 in.)	

Please correct this information in Mercury MerCruiser Service Manual #29, pages 5C-13 and 5C-14 for future reference.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.