

## service bulletin

No. 92-6

## 1988 "B" Model 35 HP FORCE Parts Book Errors

This bulletin is to advise you of part number errors in the 1988 35 HP "B" model parts book (P/N OB4191). On the Gear Housing Page, (27) Illustrations 25 and 26 are incorrect. Illustration 25 should be <u>S458023</u> bevel gear front and Illustration 26 should be <u>A458054-2</u> gear housing lower.

Please note these changes in your parts book and retain this bulletin for handy reference.

Printed in U.S.A. 92-6 592