

WARRANTY INFORMATION SERVICE INFORMATION
 PARTS INFORMATION

Bulletin No. 2002-02

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Control Board Resistor Rework

Situation

Some inventory of control board MLF15702 was produced with an incorrect resistor. This only applies to boards that are labeled "Rev. Level G". After these boards are reworked MotorGuide will add an "R" to the label indicating the board has been reworked. We will also add the word "REWORKED" and a date to the part packaging.

Warranty

USA and Canada: Return your service parts inventory of control boards MLF15702 labeled "Rev. Level G", along with completed claim forms for warranty credit (use Midas/MercNet if available).

INTERNATIONAL: Follow instructions issued by Marine Power International office or by your distributor.

Mail to: Mercury Marine
 Attn.: Warranty Department-MG SB #2002-02
 P.O. Box 1939
 Fond du Lac, WI 54936-9983

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.