

THRUSTER

# service bulletin

<ul><li>☐ WARRANTY INFORMATION</li><li>☐ PARTS INFORMATION</li></ul>	<b>√</b> SEI	RVICE INFORMATIO	)N Bul	letin No. 2002-15
Circulate to: Sales Manager A	ccounting	Service Manager	✓ Technician	Parts Manager

# **Control Board and Mosfet Replacement**

### **Models Affected**

All Variable Speed Models

#### **Situation**

The control board (DA Module) of all variable speed models was redesigned.

## Correction

When repairing any variable speed motor, it is recommended that both the control board (DA Module) and the mosfet be replaced.

# **Parts Required**

See the appropriate MotorGuide parts catalog for necessary part numbers.

#### **Dealer Parts**

Please return any stock you may have of the old control board.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

## Warranty

Parts and labor are covered during the standard two year warranty period.

Flat Rate Code: SB10 and SB05

Part Code 856Failure Code 32

**USA and Canada** – Tag and hold all old parts until 30 days after credit issued or until notified to return them.

Mail to: Mercury Marine

Attn: Warranty Department - MG SB #2002-15

P.O. Box 1939

Fond du Lac, WI 54936-9983

Fax: 1-920-929-5893

**International** – Follow instructions for old parts disposition issued by the Marine Power International office or by your distributor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Page 2 of 2 NOVEMBER 2002 2002-15