MotorGu service bulletin THRUSTER

WARRANTY INFORMATION PARTS INFORMATION

SERVICE INFORMATION

Bulletin No. 2003-07

Circulate to:

Sales Manager

Accounting

Service Manager Technician

Parts Manager

Incorrect Handle On Pontoon Models

Models Affected

FW71HP


S/N 9B107219 THRU 9B158859

Situation

Manufacturing may have installed the incorrect non extending handles on the above listed pontoon model motors.

Correction

If a non extending handle is found on the above listed models within the listed serial number range, replace the handle with P/N MBT372092. If there is no clicker on the handle, it is a non extending handle and should be replaced.



a - Clicker used on extending handle only

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE. This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Parts Required

Qty. One (1) MBT372092 Handle assembly

Warranty

MotorGuide will credit the dealer for the cost of parts and labor until August 31, 2006. Complete warranty claims listing:

- Model and serial number
- Parts as listed in this bulletin
- 0.3 hours labor
- Flat Rate Code: SB03

USA and Canada: Complete warranty claim form (use Midas/Mercnet if available).

Fax to: 1-920-929-5893 Mail to: Mercury Marine Attn: Warranty Department P.O. Box 1939 Fond du Lac, WI 54936-9983

INTERNATIONAL: Follow instructions issued by Marine Power International office or by your distributor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.