THRUSTER

service bulletin

☐ WARRANTY INFORMATION☐ PARTS INFORMATION	SERVICE INFORMATION		DN Bul	Bulletin No. 2003-04	
Circulate to: Sales Manager A	ccountina	Service Manager	Technician	Parts Manager	

Incorrect Door Knob Bushing On 21/24 Gator Mounts

Models Affected


MST921BF, MST921BH, MST924BF, MST924BH

Situation

Manufacturing may have installed a plastic door knob bushing on the above listed mounts rather than the normal metal bushing.

Correction

If the plastic door knob bushing is found in the above listed mounts, replace the bushing with a metal door knob bushing.



- a Knob
- b Bushing
- c Washer
- d Door

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Parts Required

Qty. One (1) MRK02105 door knob bushing

Qty. One (1) MRK17106 washer

Warranty

If Gator Spring mounts in stock, or received from customers do not have the proper door knob bushing, correct and submit a warranty claim. MotorGuide will credit the dealer for the cost of parts and labor until August 31, 2006.

Complete warranty claims listing:

- Model and serial number
- Parts as listed in this bulletin
- 0.3 hours labor
- Flat Rate Code: SB03

USA and Canada: Complete warranty claim form (use Midas/Mercnet if available).

Fax to: 1-920-929-5893
Mail to: Mercury Marine

Attn: Warranty Department

P.O. Box 1939

Fond du Lac, WI 54936-9983

INTERNATIONAL: Follow instruction issued by Marine Power International office or by your distributor.

Page 2 of 2 AUGUST 2003 2003-04