

parts bulletin



No. 97-2

89487 - BRUSH CARD 89486 FIELD & FRAME SERVICE REPLACEMENT PARTS FOR 87828 - HYDRAULIC PUMP MOTOR

CHANGE

Due to the availability of parts from the vendor, the brush card (89487) is **NO LONGER AVAILABLE.** To fill customer needs, a complete motor (17649A1) must be ordered.

When inventory of Field & Frame (89486) is depleted, the complete motor (17649A1) must be ordered.

Printed in U.S.A. 97-2 697