



# parts bulletin



No. 98-7

## REPLACEMENT INFORMATION FOR POWER TRIM KIT PART NUMBER 830150A2 or 830150T2

MODELS AFFECTED MERCURY/MARINER 40 (4 CYL.) & 50/55/60/60 BIGFOOT

**CHANGE:**

The size of the shock piston relief hole has changed from .093 in. to .101 in. Also for Bigfoot application Higher Tilt Relief is offered.

If you are replacing a complete Power Trim for 40 (4 Cyl.) or 50/55/60 application

**order: 830150T4**

If you are replacing a complete Power Trim for 60 Bigfoot application

**order: 855654T2**