

MERCURY OUTBOARDS

service bulletin

No. 88-9

- A. 45 HP Model Outboards –
 Serial Number B169873 thru B307896 –
 Overheat Warning Sensor
- B. 3 Cyl. 50/60 HP Model Outboards –Serial Number B110789 thru B239242 –Overheat Warning Sensor
- A. 45 HP MODEL OUTBOARDS SERIAL NUMBER B169873 THRU B307896 OVERHEAT WARNING SENSOR

45 HP outboards within the above serial number range have an overheat warning sensor that may cause the overheat warning horn to sound indiscriminately leading the operator to falsely believe the outboard is overheating.

- Order a quantity of overheat warning sensors (P/N 87–16775A2) to have on hand should you hear this complaint and to cover the 45 HP outboards you have in inventory within the above serial numbers.
- 2. Upon return of owners 45 HP outboards or for those in your inventory:
 - a. Replace the overheat warning sensor following instructions in the kit
 - b. Submit a warranty claim for the sensor and .5 hour labor for each outboard on which you replaced the sensor. Return the sensors with the warranty claims to your distribution center.
 - c. More than one outboard can be listed on a claim, but it is essential that all serial numbers are listed.

B. 3 CYL. 50/60 HP MODEL OUTBOARDS – SERIAL NUMBER B110789 THRU B239242 – OVERHEAT WARNING SENSOR

50/60 HP outboards within the above serial number range have an overheat warning sensor that may cause the overheat warning horn to sound indiscriminately leading the operator to falsely believe the outboard is overheating.

- Order a quantity of overheat warning sensors (P/N 87–19541A2) to have on hand should you hear this complaint and to cover the 50/60 HP outboards you have sold or have in inventory within the above serial numbers.
- 2. Upon return of owners 50/60 HP outboards or for chose in your inventory:
 - a. Replace the overheat warning sensor following instructions in the kit.
 - b. Submit a warranty claim for the sensor and .5 hour labor for each outboard on which you replaced the sensor. Return the sensors with the warranty claims to your distribution center.
 - More than one outboard can be listed on a claim, but it is essential that all serial numbers are listed.

We sincerely regret any inconvenience this may cause you. We appreciate all dealer efforts to correct the above problems and ensure boating satisfaction to our mutual customers.

Printed in U.S.A. 88-9 388