



# service bulletin


No. 91-9

## AutoBlend Inlet Check Valve P/N 21-811008

## **All AutoBlend Oil Injection Systems**

The umbrella style inlet check valves for all AutoBlend units are available by ordering P/N 21-811008. A package contains two check valve assemblies (umbrella valve and seat) and one rubber gasket. One kit is required to service both inlet check valves installed in the AutoBlend unit.

The leak test for the inlet check valves is in section 8 of the 45/50 (4 cyl.) and 50/60/70 (3 cyl.) service manual, P/N 90-86135--5. Replacement of the inlet check valves is not always necessary. Cleaning the check valve may be all that is required for proper operation.



a - Inlet Check Valve Assemblies

Figure 1. Bottom View of AutoBlend with Oil Pickup Tube Removed

### QUICKSILVER:

P/N 21-811008 Inlet Check Valve Kit contains: two check valve assemblies (umbrella valve and seat) one rubber gasket

#### WARRANTY:

Normal 12 month warranty applies.

Printed in U.S.A. 91-9 291