

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

40/50/60 EFI FourStroke and OptiMax Ignition Coil Service Repair

NOTICE
Revised January 2014. This bulletin supersedes the previous bulletin number 2009-26 December 2009.

Models Affected

Models Covered	Serial Number
Mercury/Mariner	
40–60 FourStroke	0T980000–1C104332
75–115 OptiMax	0T801000–1B776166
135–200 OptiMax	1B421465–1B776910
200–250 OptiMax	1B504989–1B777601
175 Pro XS OptiMax	1B516339–1B785148
225–250 Pro XS OptiMax	1B426560–1B776272

Situation

You may receive reports of ignition coils failing due to stress caused by normal engine thermal cycles. This will cause the affected cylinder to lose spark either intermittently or completely.

Correction

When servicing the failed ignition coil on an engine in the above affected range, please replace the ignition coils as a set; all 3, 4, or 6 ignition coils.

Part Interchangeability

Coil P/N 883778A01 is superseded by 883778A02

Coil P/N 879984T00 and 879984A1 is superseded by 879984T01

Dealer Parts Inventory or Dealer Outboard Inventory

USA customers: To return coil P/Ns 883778A01, 879984T00 or 879984A1 in your inventory please file a normal warranty claim and return the parts to Mercury Marine Warranty Department.

Non-USA customers: Return any coil P/Ns 883778A01, 879984T00 or 879984A1 in your inventory to the appropriate distribution center for credit. Follow the normal warranty parts procedure.

Warranty

Complete a warranty claim listing:

- Outboard engine serial number
- Flat rate labor allowance
- 3, 4, or 6 coils and P/N – per engine requirement
- Part code: 306

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

- Failure code: 00

Mercury Marine will credit the dealer for engines under warranty in the above serial number ranges, for the cost of parts and labor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.