



# Service Bulletin

Bulletin No. 2013-18  
OEM No. 2013-11

Circulate to:  Sales Manager  Accounting  Service Manager  Technician  Parts Manager

## Mercury/Mariner 4–5 HP Two Stroke Fuel Tank Revision

### Models Affected

Models Covered	Serial Number
4–5 HP Mercury/Mariner Two Stroke engines	USA - 1B564133 and below
4–5 HP Mercury/Mariner Two Stroke engines	Belgium - Box date 9/2008 and prior

### Scope

Worldwide

### Situation

Mercury Marine has revised the integral fuel tank for the above listed models. The current integral fuel tank for these models will be no longer available (NLA) as supply of the components is exhausted. The replacement assemblies include a revised integral fuel tank, fuel cap, and top cowl.

Reference the chart below for the appropriate fuel tank/top cowl kit. Decal sets are not included in the below mentioned kits. Refer to the electronic parts catalog for the appropriate decal set.

Engine Model	Current Fuel Tank	New Fuel Tank Kit
Mercury 4–5 HP Two Stroke	824964A03 (NLA)	8M0059125
Mariner 4–5 HP Two Stroke	824964A03 (NLA)	8M0059218

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.