



PARTS & SERVICE DIV.

MERCUISER SERVICE BULLETIN

Section: XII (Service
Bulletins)

Number: 19

Date : 9/29/64

A. Power Tilt Installation - MerCr. II

A. MERCUISER II POWER TILT INSTALLATION

(For Installation Section II)

When installing Power Tilt on MerCruiser II Stern Drive Units, Serial No. 1778954 and above, remove one spring on each side of reverse hook assembly, as shown in Figure 1.




Figure 1. Reverse Hook Assembly Spring