

WARRANTY INFORMATION

SERVICE INFORMATION

MCM 3.0L Flame Arrestor Decal

Models

MCM 3.0L Sterndrive Engine: S/N 0L605518–0L638481.

Situation

The ignition timing listed on the original flame arrestor decal says 1° ATDC. This is not correct. The correct ignition timing should be 2° ATDC.

Correction

Order 1 Specification Patch Decal for each engine that you service within the serial number range given. Decal Patch is applied directly on the original flame arrestor decal.

Part Required

P/N 37–856602 1 Decal Specification Patch.

Warranty

Fill out warranty claim and send it to your normal warranty processing center.

Warranty Code and Labor: None 0.2 Hours.



75824

a - Place Decal Patch Here