

Circulate to:     Sales Manager     Accounting     Service Manager     Technician     Parts Manager

## New Spark Plug Wire Locations on Distributor Cap

### Models Affected

Models	Serial Number Or Year
3.0 TKS and MPI	1A337296 and above


### Situation

The spark plug wires on the distributor have been relocated. A new decal on the distributor cap notes this change to prevent confusion if using current literature or comparing to prior engines. The engine firing order remains unchanged.

### Correction

#### 1A337296 AND ABOVE


Follow the new decal for spark plug wire locations on engines with serial number 1A337296 and above.



40075

#### 1A337295 AND BELOW

Spark plug wire locations on engines with serial number 1A337295 and below.



40074

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.