

PERFORMANCE OUTBOARDS

service bulletin

No. 96-9

Hi-Performance 2.4 Litre Rod Bearings

The parts manuals and micro fiche cards for the 2.4 litre Hi-Performance outboards list rod bearing part number 31-17514A2 which is incorrect. Use of this bearing in the 2.4 litre Hi-Performance engines could result in premature failure at high RPM.

Instead, use the 2.5 litre bearing which incorporates better rollers (P/N 31-821146A1).

The parts manuals and micro-fiche cards will be changed to reflect the new number when reprinted.

Printed in U.S.A. 96-9 296