

Service Bulletin

Outboard No. 2008-02 OEM No. 2008-02

Circulate to:

Sale	s Manage
------	----------

Accounting

Service	Manage
---------	--------

Technician

Parts Manager

Mercury Racing Flywheel Puller/Lifting Ring (91-895343T03)

Models Affected:


Models	Serial Number
Verado 350	All

Situation:

A new flywheel puller/lifting ring tool (**91-895343T03**) is required to lift the Verado 350 SCi engine from its shipping crate.

The new tool is designed to lift the Verado 350 SCi engine without damaging engine components.

IMPORTANT: The Mercury Racing flywheel puller/lifting ring tool (91-895343T03) must be used to lift the Verado 350 SCi powerhead/engine or damage to the engine or flywheel fan may occur.



a - Lifting ring

b - Puller/lifting base

c - Flywheel fan

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.