

## service bulletin

No. 95-2

## 1996 Product Information - Sport Jet 95XR and 120XR

The 1996 model line of Sport Jet 95XR and 120XR has major powerhead changes. Listed below are changes of interest to Service Technicians:

- Connecting rod is now top guided. This change has resulted in new pistons, connecting rod bearings, crankshaft, and cylinder assembly components.
- New electrical system is incorporated. It is new CDM ignition system which eliminates switch box. Capacitor and SCR, which were in switch box, are now located in ignition coil.
- Lifting eye which threads in flywheel is now necessary for installation/removal of outboard/ powerhead.
  - Part number of lifting eye is 91-90455.
- 4. Cylinder head bolt torque has changed to "TORQUE and TURN" method on 75 thru 120HP models. Cylinder head bolts are now torqued in sequence to 120 lb/in (13.5 N·m). After final torque, turn each bolt an additional 90 degrees.

Another point worth mentioning is that these bolts MUST be oiled before installation – both threads and underside of head.

This procedure is used on connecting rod screws starting with 1995 models of 40 thru 120HP.

5. Remote electric harness connection at power-head is located at rear starboard corner of power-head. This applies to 75, 90, and 120HP models. Impact of this change is requirement of remote electric cable from dashboard to be at least two feet longer than previous cable. In most cases there is enough length but, it is worth noting and checking before installation of outboard on boat.

All of above information is in the new 1996 Technician's Handbook. Main purpose of this bulletin is to provide information which needs some emphasis for Service Technician.

Printed in U.S.A. 95-2 595