Motor Guide MARINE

THRUSTER

service bulletin

☐ WARRANTY INFORMATION☑ PARTS INFORMATION	SERVICE INFORMATIO	DN Bulletin No. 2002-1
Circulate to: Sales Manager	Accounting Service Manager	✓ Technician ✓ Parts Manage
▲ = Revised August 2002. This bu	Illetin supercedes the previous I	bulletin 2002-11 July 2002.

New Control Board Part Numbers

Models Affected

All Variable Speed Trolling Motors

Situation

The below listed control boards have been redesigned to enhance durability.

Dealer Parts Inventory

USA customers: Return any unused service parts inventory of the below listed control boards, along with a completed warranty claim form (use MercNET if available and return a copy of the completed claim with the parts).

Mercury Marine Attn: Warranty Department – MG SB #2002-11 W6250-9A Pioneer Road Fond du Lac, WI 54935

Non-USA customers: Return any unused service parts inventory of the below listed control boards to the appropriate distribution center for credit. Follow the normal return parts procedure for warranty parts. Please make reference to MG SB #2002-11.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Parts Required A

* Old Board #'s	New Board #'s	Voltage
MAF15702F	MAF15712	36
MAF15703H	MAF15713	24
MAF15704D	MAF15714	12
MAF15705C	MAF15715	36 Pinpoint Ready
MAF15706C	MAF15716	24 Pinpoint Ready
MAT15701D	MAT15711	12
MAT15702D	MAT15712	24
MAT15703E	MAT15713	36
MJF15702	MJF15712	24
MJF15703	MJF15713	12

^{*} Older versions of these control boards that supersede to part numbers listed in the "Old Board #'s" column may also be returned under the terms of this service bulletin.

Page 2 of 2 AUGUST 2002 2002-11R1