

service bulletin

TO: SERVICE MANAGER
MECHANICS
PARTS MANAGER

No. 97-6

HP 900 SC EXHAUST HEADER AND WARRANTY INFORMATION

MODELS AFFECTED

1998 900 SC Hi-Performance engine.

EXHAUST HEADERS

Because most of these MC 900 SC packages will be custom installations, exhaust headers must be purchased separately directly from a header manufacturer. Mercury Hi-Performance suggests CMI exhaust systems since the majority of our testing and prior experience is with this company.

> Custom Marine Inc. 138 Water St. Menasha, WI. 54952 Phone (414)-722-7084 Fax (414)-722-4530

SALES AND SERVICE

All sales and service issues related to the exhaust systems should be addressed by the header supplier.