

TO: PARTS MANAGER
SERVICE MANAGER

No. 96-1

Hino Turbocharger

Models

Hino WO6D-TI-II

Ordering Part

When ordering the turbine case for replacement it should be noted that on page 71 of the Quicksilver Parts Catalog, 90-820723, that part number 831111430 is incorrect, for item reference number 21 (Case-Turbine). The correct part number is 831111640.

Micro-Fiche card number 71, grid F 4, item number 21(Case-Turbine) the correct part number is 831111640.