


service bulletin

TO: SERVICE MANAGER ☐ TECHNICIANS ☐ PARTS MANAGER ☐


No. 88-12

MerCruiser 215E Shift Actuators



17477

Old Style Actuator, 54240A4



New Style Actuator, 54240A7

As of June 1, 1988 there will no longer be any type of a repair program or replacement program for the 215E shift actuator by Mercury Marine. Because of availability of parts and repair facilities Mercury Marine will be unable to continue such a program.