

## Service Bulletin

**Bulletin No. 2004-62** 

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

## CMD Service Bulletin 2004-02 - 1.7 Liter Piston Change

## **Models Affected**

Application	Model	Serial No.
CMD	1.7 MS 120	0M057592 and above
CMD	1.7 MI 120	0M057592 and above

## Situation

A running change was made in June of 2002 to the piston design of the 1.7 liter Isuzu base engine. The design change was made for all 1.7L blocks including automotive, marine, and industrial applications. The previous part numbers assigned to the three (3) piston sizes are no longer available. Old and new part numbers are as follows:

Grade	Old Number	New Number
A	882692	882692001
В	882693	882693001
С	882694	882694001

Visually there is no way to differentiate the old-style versus the new-style pistons. It is recommended by Cummins MerCruiser Diesel that when replacement of one or more pistons for engines prior to serial number 0M057592 is required, all of the pistons should be replaced.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.