

Service Bulletin

Bulletin No. 2005-09 OEM No. 2005-09

```
Circulate to:
```

Sales Manager

```
Accounting
```

Service Manager

Technician

Parts Manager


Water Shutters Approved for 496 CID Sterndrive Models

Models Affected

Models Affected	Serial Number Or Year
496 MAG, 496 MAG HO Sterndrive Models	All Models

Situation

Exhaust water shutters are now approved for use in 496 MAG and 496 MAG HO sterndrive applications. The exhaust water shutters have also been added to the 496 MAG and 496 MAG HO Exhaust Y Pipe Kit.



The water shutters should be inspected every 300 hours or 3 years as part of routine maintenance. Replace the water shutters as required.

Parts Required / Ordering Replacement Parts

Qty.	Description	Part Number
1	496 MAG, 496 MAG HO Exhaust Y Pipe Kit	807130A21
2	Water Shutter Kit	807166A1

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.