

PERFORMANCE OUTBOARDS

service bulletin

No. 96-8

Hi-Performance Outboard Cylinder Head Modifications

Powerhead failures caused by increased compression due to modified cylinder heads will not be considered for warranty. Although there is some performance increase with modified heads, the engine becomes extremely sensitive to detonation.

Engines operated with modified cylinder heads are classified as modified product and related failures are not covered under the original warranty.

The following will be returned to the dealer with a warranty rejection. Failed powerheads received:

- with modified cylinder heads
- with cylinder heads that were not on the engine at time of failure
- without cylinder heads