

- WARRANTY INFORMATION SERVICE INFORMATION
 PARTS INFORMATION

Bulletin No. 2003-01

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

▲ = Revised May 2003. This bulletin supercedes the previous bulletin 2003-01 January 2003.

Major Motor Mount Components Are No Longer Available (NLA)

▲Models Affected

All motors using 16, 20, and 23 mounts

▲Situation

The components of the clutch channel assembly (clutch channel, top channel and clutch insert assemblies) for the 16, 20, and 23 mounts are No Longer Available (NLA).

Correction

To repair the unit, parts must be ordered individually rather than by a whole assembly.

ATTENTION:

Pay close attention to the **model** when ordering the black clutch channel (MRK36101), white clutch channel (MRK36102), and the clutch insert (MRK07901) because there are multiple uses for these parts. New parts will be painted black or white. Any gray parts will be superseded to black components and may need to be painted. Paint is not included.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Parts Required

Models Affected	NLA Part Number	Description	Replacement Parts		
			Qty	Part Number	Description
20 Black Bow Mount	MRK330819	Top Channel Clutch Assembly	1	MRK30810	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 White Bow Mount	MRK330829	Top Channel Clutch Assembly	1	MRK30814	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
23 Black Bow Mount	MRK330839	54" Top Channel Clutch Assembly	1	MRK30812	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
23 White Bow Mount	MRK330849	Top Channel Clutch Assembly SW	1	MRK30815	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Models Affected	NLA Part Number	Description	Replacement Parts		
			Qty	Part Number	Description
20 Gray Bow Mount	MRK330859	Top Channel Gray	1	MRK30814	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 Black Bow Mount	MRK30801	Top Channel Black	1	MRK30814	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 Black Bow Mount	MRK36101	Clutch Channel Black	1	MRK30810	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 Black Bow Mount	MRK07901	Clutch Insert	1	MRK30810	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

MAJOR MOTOR MOUNT COMPONENTS ARE NO LONGER AVAILABLE (NLA)

Models Affected	NLA Part Number	Description	Replacement Parts		
			Qty	Part Number	Description
23 Black Bow Mount	MRK30804	23 Mount Top Channel Black	1	MRK30812	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
23 Black Bow Mount	MRK36101	Clutch Channel Black	1	MRK30812	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
23 Black Bow Mount	MRK07901	Clutch Insert	1	MRK30812	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 White Bow Mount	MRK30802	Top Channel White	1	MRK30814	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.
 This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Models Affected	NLA Part Number	Description	Replacement Parts		
			Qty	Part Number	Description
20 White Bow Mount	MRK36102	Clutch Channel White	1	MRK30814	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 White Bow Mount	MRK07901	Clutch Insert	1	MRK30814	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
23 White Bow Mount	MRK30805	54" Top Channel White	1	MRK30815	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
23 White Bow Mount	MRK36102	Clutch Channel White	1	MRK30815	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

MAJOR MOTOR MOUNT COMPONENTS ARE NO LONGER AVAILABLE (NLA)

Models Affected	NLA Part Number	Description	Replacement Parts		
			Qty	Part Number	Description
23 White Bow Mount	MRK07901	Clutch Insert	1	MRK30815	Top Channel
			1	MRK36105	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 Gray Bow Mount	MRK308066	Top Channel Gray	1	MRK30810	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 Gray Bow Mount	MRK361036	Clutch Channel Gray	1	MRK30810	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
20 Gray Bow Mount	MRK07901	Clutch Insert	1	MRK30810	Top Channel
			1	MRK36104	Clutch Channel
			1	MRK07905	Clutch Insert
			2	MRK02504	Clutch Bolt
			2	MXT01101	Clutch Washer
			2	MRK08204	Clutch Knob
▲16 Black Bow Mount	MRK07901	Clutch Insert	1	MRK07906	Clutch Insert

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.
 This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.