



# parts bulletin



No. 95-7

## FORCE OUTBOARD AND SPORT JET MODELS

### STATOR AND REV LIMITER CHART

HP	MODEL & MODEL YEAR	ORIGINAL STATOR	SUPERSEDED TO	REQUIRES
40/50 FORCE	1992C To 1994-1/2 S/N E000001 Thru E065560	398-818535A14	398-9710A47	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065561 Thru E138599	398-818535A14	398-9710A47	Does Not Need Voltage Regulator Change
70 FORCE	1991B To 1994-1/2 S/N E000001 Thru E065371	398-8778A10 or 398-8778A26	398-9873A35	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065372 Thru E138599	398-8778A29	398-9873A32 or 398-9873A35	Does Not Need Voltage Regulator Change
90 FORCE	1991H To 1994-1/2 S/N E000001 Thru E065504	398-8778A10 or 398-8778A26	398-9873A35	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065505 Thru E138599	398-8778A29	398-9873A32 or 398-9873A35	Does Not Need Voltage Regulator Change
120 FORCE	1991D To 1994-1/2 S/N E000001 Thru E065486	398-8778A23	398-9710A45	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065487 Thru E138599	398-8778A27	398-9710A45	Does Not Need Voltage Regulator Change

<b>90 SPORT JET</b>	<b>1993 S/N E009600 Thru E031401</b>	<b>398-8778A10</b>	<b>398-9873A35</b>	<b>Needs 815279T5 Voltage Regulator and 821889A36 Rev Limiter</b>
	<b>1993 To 1994-1/2 S/N E031402 Thru E067404</b>	<b>398-8778A10</b>	<b>398-9873A35</b>	<b>Needs 815279T5 Voltage Regulator</b>
	<b>1994-1/2 S/N E067405 Thru E095087</b>	<b>398-8778A29</b>	<b>398-9873A32 or 398-9873A35</b>	<b>Does Not Need Voltage Regulator or Rev Limiter Change</b>
<b>120 SPORT JET</b>	<b>1995 S/N E095088 Thru E141088</b>	<b>398-818535A14</b>	<b>398-9710A47</b>	<b>Needs 821889A36 Rev Limiter</b>