

## parts bulletin



No. 95-11

## CYLINDER REBUILD KIT (813432A2) SHOCK ROD (813427--2)

## **MODEL**

Mercury/Mariner/Tracker 40 thru 60 H.P.

## **CHANGE**

When existing stock of 813432A2 (Cylinder Rebuild Kit) and 813427--2 (Shock Rod) is depleted order your replacement part from the chart below:

813427A1 **MANUAL** SHOCK ROD ASSY. 813427A2 **BEACHING** SHOCK ROD ASSY.

Printed in U.S.A. 95-11 1095