

TO: PARTS MANAGER
SERVICE MANAGER

No. 93-1


A. CHANGE TO REMOTE CONTROL HANDLE P/N 92744A2

Models

Remote controls that use curved handle P/N 92744A2

Change

We can not get the original replacement handle any more. The new replacement handle is slightly LONGER than the original one. On Dual Console Controls, you may want to change both handles so they are the same length. The part number for the new handle is the same as the original handle part number.



52051