





TO: PARTS MANAGER

## **QUICKSILVER** MARINE PARTS AND ACCESSORIES

No. 98-7

## Heat Exchanger Clamps For D-Tronic D2.8L Diesels

**Models** 

MCM / MIE D2.8L D-Tronic Diesels

## **Replacement Clamps**

There is a new style replacement clamp that can be used on the heat exchanger for the D-Tronics D2.8L Diesel. If the original clamps fail, check the underneath side of the bracket that the heat exchanger sits on to make sure that the casting is smooth and does not have a sharp edge on the rear of the bracket. If a sharp edge exists, grind the casting smooth and then replace the original clamps with the new heat exchanger clamps that will automatically hold tension.

New Heat Exchanger Clamp P/N 54-803620