

# Engine Wiring Harness Repair Kits – 135/150/175/200 Verado L4 and 200/225/250/275/300/350 SCi Verado L6

# Situation

This service bulletin releases the engine wiring harness repair kits available for the above listed models. These kits are to be used for the warranty repair of engine wiring harnesses and are an economical option for a nonwarrantable repair. These kits are intended to eliminate the unnecessary replacement of complete engine wiring harnesses.

NOTE: Installation instructions are included with each harness repair kit.

87934	879346A31 CAN 1 Harness Repair Kit (10 Pin)				
100			Where Used		
	<image/> <image/>	Verado: CAN 1 te	erminator		
Ref.	Description	Qty.	Part Number		
а	CAN 1 repair harness (10 pin)	1	NSS		
b	Crimp splice 22-18 AWG	5	8M0045338		

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

87934	879346A32 Packard Repair Kit (2 Pin), Black				
		Where Used			
	aabbccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccccc<	vent canister purge va	sensors, vent canister switch, lve, knock resistor, neutral ensor, CAN 2 terminator		
Ref.	Description	Qty.	Part Number		
а	Packard repair harness (2 pin), black	1	NSS		
b	Crimp splice 22-18 AWG	2	8M0045338		

### 879346A33 Packard Repair Kit (2 Pin), White

		Verado: Knock :	Where Used
Ref.	Description	Qty.	Part Number
а	Packard repair harness (2 pin), white	1	NSS
b	Crimp splice 22-18 AWG	2	8M0045338

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

87934	16A34 Packard Repair Kit (3 Pin), Black		
		<u> </u>	Where Used
	<image/> <image/>	Verado: Trim relay h	arness, power steering
Ref.	Description	Qty.	Part Number
а	Packard repair harness (3 pin), black	1	NSS
b	Crimp splice 22-18 AWG	3	8M0045338

87934	879346A36 Packard Repair Kit (4 Pin)				
	Where Used		Where Used		
	<image/> <image/>	Verado: Diagnosti	cs connector		
Ref.	Description	Qty.	Part Number		
а	Packard repair harness (4 pin)	1	NSS		
b	Crimp splice 22-18 AWG	4	8M0045338		

87934	879346A37 Packard Repair Kit (5 Pin)				
			Where Used		
	<image/> <image/>	Verado: Shift ad	ctuator		
Ref.	Description	Qty.	Part Number		
а	Packard repair harness (5 pin)	1	NSS		
b	Crimp splice 22-18 AWG	5	8M0045338		

## 879346A38 Packard Repair Kit (6 Pin)

	Where Used
Automatic   Automatic   Automatic	Verado: SmartCraft boat harness, FSM harness

	43171		
Ref.	Description	Qty.	Part Number
а	Packard repair harness (6 pin)	1	NSS
b	Crimp splice 22-18 AWG	4	8M0045338
с	Crimp splice 16-14 AWG	2	896711T

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.


1.7.33		w	/here Used
a	<image/> <image/>	pressure, fuel rail pres	essure, oil pressure, block ssure sensors (350 SCi)
		Qty.	Part Number
Ref.	Description		
Ref.	Packard repair harness (3 pin)	1	NSS
		1 3	NSS 8M0045338
a b	Packard repair harness (3 pin)		
b	Packard repair harness (3 pin) Crimp splice 22-18 AWG	3	

	a B B B B B B B B B B B B B	Verado: Cam positi	on sensor
	43173		
Ref.	43173 Description	Qty.	Part Number
Ref.		Qty.	Part Number NSS

			Where Used	
	<image/> <image/>	Verado: Boost v	/alve	
ef.	Description	Qty.	Part Number	
a	Boost valve repair harness (4 pin)	1	NSS	
	Crimp splice 22-18 AWG	4	8M0045338	

	<u> </u>		Where Used
	<image/> <image/>	Verado: Electronic ti	nrottle control (ETC)
Ref.	Description	Qty.	Part Number
а	Electronic throttle control repair harness (6 pin)	1	NSS
b	Crimp splice 22-18 AWG	6	8M0045338

87934	879346A45 Manifold Air Temperature (MAT) Repair Kit (2 Pin)			
		Where Used		
	<image/> <image/>	Verado: Manifold air	temperature (MAT) sensor	
Ref.	Description	Qty.	Part Number	
а	Manifold air temperature (MAT) repair harness (2 pin)	1	NSS	
b	Crimp splice 22-18 AWG	2	8M0045338	




879346A47 Cowl Tilt Switch Repair Kit (3 Pin)			
		Where Used	
	<image/> <image/>	Verado: Cowl tilt swi	tch, trim sensor harness
Ref.	Description	Qty.	Part Number
а	Cowl tilt switch repair harness (3 pin)	1	NSS
b	Crimp splice 22-18 AWG	3	8M0045338

#### 879346A48 Relay Base Repair Kit (White)

			Where Used
	<image/> <image/>	Verado: Fuel pump	
Ref.	Description	Qty.	Part Number
а	Relay base repair harness (white)	1	NSS
b	Crimp splice 22-18 AWG	2	8M0045338
с	Crimp splice 16-14 AWG	2	896711T

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

and the second			Where Used	
	<image/> <image/>	Verado: Fuel ir	njector	
	Description	Qty.	Part Number	
	Fuel injector repair harness	1	NSS	
	Crimp splice 22-18 AWG	2	8M0045338	



87934	6A53 Alternator Repair Kit (2 Pin)		
		Where Used	
	<image/> <image/>	Verado: Alternato	r
Ref.	Description	Qty.	Part Number
а	Alternator repair harness (2 pin)	1	NSS
b	Crimp splice 16-14 AWG	2	896711T